



## LinkPlay Driver Update Notes

The 4Drivers Linkplay driver was created containing some non-sequential internal connection IDs. This in most drivers has no impact at all, it is a practice over the years we have noticed some non conformities in the keying and we have been adapting the code to circumvent

We decided to normalize these IDs and connections in version 1100. The input and multiroom connections between devices will be lost, requiring the dealer to redo them.

Before upgrading, make a note of the connections of the divers and after upgrading, reconnect them